

BUNN® CWTF-TC BREWING & CLEANING INSTRUCTIONS

BREWING



1. Insert a BUNN® filter into the funnel.



2. Pour in fresh coffee.



3. Shake funnel gently to level grounds.



4. Slide funnel into the funnel rails of the brewer.



5. Place an empty decanter under the funnel.



6. Place the "ON/OFF" switch in the "ON" upper position.



7. Momentarily press and release the "START" switch.



8. When brewing is complete, discard the grounds and filter.

CLEANING the BREWER



1. Clean and sanitize the funnel.



2. Use a clean damp cloth rinsed in mild, non-abrasive detergent to clean the sprayhead panel.



3. Remove the sprayhead.



4. Clean mineral deposits and rinse. Make sure all holes are open.



5. With the sprayhead removed, insert a deliming spring into the sprayhead tube until approximately two inches of the spring remain visible. Saw back and forth five or six times to loosen any lime deposits.



6. Flush the tube by running a brew cycle using an empty funnel and decanter. When the cycle is completed, replace the sprayhead.



7. Use a clean damp cloth rinsed in mild, non-abrasive detergent to clean all outer surfaces.



Brewing and cleaning procedure also applies to the CWTF Twin TC.